




| PART | QTY. | ITEM    |
|------|------|---------|
| A    | 4    | M6X55mm |
| B    | 2    | M6X40mm |
| C    | 4    | M6X30mm |
| D    | 5    | M6X25mm |
| E    | 1    | M6X20mm |

| PART | QTY. | ITEM      |
|------|------|-----------|
| F    | 4    | M4X6mm    |
| G    | 4    | M3.5X11mm |
| H    | 2    | M4        |
| I    | 4    | M8X18mm   |
| J    | 1    |           |



## MULTI FUNCTIONS COMPUTER TABLE ZITA PLUS 12-0050 ASSEMBLY INSTRUCTION

Thanks for purchasing one of our products, please read carefully the assembly instructions before the installation (Attention: Do not tighten the screws before all screws are in place).

